


CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

THERE IS NO CORNER OF RECORD. THIS IS A NEW SECTION SUBDIVISION MONUMENT SET FOR THIS SURVEY.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE OF RECORD.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____
State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER


CORNER IS IN MAHOGANY ON STEEP SOUTH SLOPE ABOUT 100 FT. WEST OF A VERTICAL ROCK FACE.

Signature	Title	Division	Headquarters	Date
-----------	-------	----------	--------------	------

CORNER RECORD (PERPETUATION)

MENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET A 1-1/4" x 30" ALUMINUM PIPE, 21" DEEP WITH A 3-1/4" ALUMINUM CAP WITH THE FOREST SERVICE "LOGO" STAMPED:
MONUMENT SETS ON LINE 493.1 FT. SOUTH OF TRUE POINT.



ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

POSTED MONUMENT AND BOUNDARY SIGNS ON NEARBY TREES.

Work Done By: J. RUSSELL MANNING Title: LAND SURVEYOR Date: 9/16/92
REMARKS

CORNER CERTIFIED CORRECT.

